PRINCE GEORGE'S COUNTY

HISTORIC SITE SUMMARY SHEET

Survey #: P.G.	#68-21 Building Date: 1918
Building Name: _	William H. Carlton House
Location: 5110	Emerson Street, Emerson, Maryland
Description	Private/Residence/Unoccupied/Good/Inaccessible

The William H. Carlton House is a two story, rectangular, gable roof frame dwelling situated on a town lot. The three bay south (main) gable end has entrance in the third bay through a modern door. Windows are 1/1 sash. Both entrance door and windows have wooden architrave surrounds. The first and second bays are in a two story flat roof projecting bay. The cornice continues across the front gable end, giving the gable a pedimented appearance. The entrance is sheltered by a two bay shed roof porch which wraps around and continues for two bays across the east facade. The porch roof has projecting rafter ends and rests on slender rectangular posts. The house is covered with yellow painted asbestos shingle, rests on a brick foundation, is roofed with asphalt shingle and has overhanging eaves with projecting rafter ends. The two bay east facade has a corbelled brick chimney centered at the gable ridge. The first bay has a square window with small square sidelights lighting the interior stair. The second bay is slightly set back and has a shed roof, one story, one bay addition with a 2/2 window. The two bay west facade has a projecting semioctagonal one story bay in the first bay. The rear of the house is dominated by a two-by-one-bay, two story gable roof addition with a corbelled brick interior end chimney. On the west side of the addition is an octagonal, one story addition of rusticated cement block which houses the furnace. The interior of the house has a east side hall and two west parlors. The open-string stair has turned balusters and a turned and chamfered newel post. Banded molding with corner blocks surrounds the interior doors and windows. There is a corner fireplace with a brick surround in the living room. There is no basement.

Significance

The William H. Carlton House is significant as a modest suburban dwelling built in a rapidly urbanizing area of the County early in the twentieth century. The house was built in East Hyattsville for William H. Carlton around 1918. Carlton worked at the Washington, D.C. Pumping Station. The area of the County around the north-eastern border of the District of Columbia was, in the early twentieth century, becoming an area of suburbs. Workers employed in Washington, D.C. could travel to work from the suburbs by train or electric trolley. The house appears to have had a significant addition to the rear at a date later than that of its initial construction. It had a low tax value in 1918, indicating a dwelling more modest than its present size. Its style, with overhanging eaves, projecting rafter ends and use of casement windows, is typical of houses built in the County in the early twentieth century.

Acreage: 33,614 square feet

Survey No. FC: 68-21

Maryland Historical Trust State Historic Sites Inventory Form

DOE __yes __no

Magi No.

1. Nam	e (indicate pr	eferred name)		
historic Will	iam H. Carlton Hous	se		
and/or common				
2. Loca	ition			
street & number	5110 Emerson St	reet		not for publication
city, town Edi	monston	vicinity of	congressional district	5
state Md.		county	Prince George's	
	sification			
Category district _X building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park _X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresse	s of <u>all</u> owners)
name Bria	n Wonderly			
street & number	5110 Emerson Stree	et	telephone n	o .:
city, town Edi	monston	state	and zip code Md.	20781
5. Loca	ation of Leg	al Description	on	
courthouse, regis	stry of deeds, etc.	rince George's Count	y Courthouse	liber 5624
street & number	Main Street			folio 564
city, town	Upper Marlboro		state	Md.
6. Repi	resentation	in Existing	Historical Surv	reys
N.A.				
date			federalstat	e county loca
depository for su	rvey records	·····		
city, town			state	

7. Description Survey No.f 68-21 ondition Check one Check one

Condition		Check one	Check one	
excellent	deteriorated	unaltered	X original site	
X good	ruins	X altered	moved date of mo	ve
fair	unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The William H. Carlton House is a two story, rectangular, gable roof frame dwelling situated on a town lot. It is located in a subdivision of mixed early twentieth century dwellings and those of a later date.

The three bay south (main) gable end has entrance in the third bay through a modern door. Windows on the facade are 1/1 double-hung-sash. Both entrance door and windows have wooden architrave surrounds. The first and second bays are in a two story flat roof projecting bay with a boxed wood cornice. The cornice continues across the front gable end, giving the gable a pedimented appearance. There is a rectangular louvered opening in the upper gable. The entrance is sheltered by a two bay shed roof porch which wraps around and continues for two bays across the east facade. The porch roof has projecting rafter ends and rests on slender rectangular posts.

The house is covered with yellow painted asbestos shingle and rests on a brick foundation. The roof is covered with asphalt shingle, and has overhanging eaves with projecting rafter ends.

The two bay east facade has a corbelled brick chimney centered at the gable ridge. The first bay has a square window with small square sidelights, which lights the interior stair landing. The second bay of the main block is slightly set back and has a shed roof, one story, one bay addition with a 2/2 window. The two bay west facade has a projecting semi-octagonal one story bay in the first bay. The north (rear) of the house is dominated by a two-by-one-bay, two story gable roof addition with a corbelled brick interior end chimney. A shed roof, one bay porch on the east side of this addition shelters a rear entrance. On the west side of the addition is an octagonal, one story addition of rusticated cement block which houses the furnace. The roof of this addition has the same projecting rafter treatment used around the building's roofline.

The interior of the William H. Carlton house has a east side hall and two west parlors. The open-string stair has turned balusters and a turned and chamfered newel post. Banded molding with corner blocks surrounds the interior doors and windows. There is a corner fireplace with a brick surround in the living room. The building has no basement.

1400 1500 1600 1700	-1799 -1899	are agX are are are	of Significance cheology-prehistoric cheology-historic riculture chitecture the mmerce mmunications	oric	con con eco edu eng exp ind	nmunity servati nomics ication jineerin	y plannir on s	ng - - - -	law liter mili mu: phil	rature tary	s s s t	science sculpture social/ numanitarian heater ransportation other (specify)
Specific	dates	191	.8	•	Builder	/Archi	tect					
check:	aı	nd/or	Criteria: _		B B			E	F	G		
	Leve:	l of S	ignificance:		nation	al _	_state	e _	_local			

Survey No. pc 68-21

Prepare both a summary paragraph of significance and a general statement of history and support.

The William H. Carlton House is significant as a modest suburban dwelling built in a rapidly urbanizing area of the County early in the twentieth century. The house was built in East Hyattsville for William H. Carlton around 1918. East Hyattsville was platted by J. Harris Rogers in 1907. Carlton was an unskilled worker at the Washington, D.C. Pumping Station. The area of Prince George's County around the northeastern border of the District of Columbia was, in the early twentieth century, becoming an area of residential suburbs. Skilled and unskilled workers employed in Washington, D.C., could travel to work from the suburbs by train or electric trolley.

The William H. Carlton House appears to have had a significant addition to the rear (north) at a date later than that of its initial construction. It had a relatively low tax value of \$360 in 1918, 4 indicating a dwelling more modest than its present size. The style of the dwelling, with overhanging eaves, projecting rafter ends and use of casement windows, is typical of houses built in the County in the early twentieth century. 5

Notes

8. Significance

- Tax Assessments, Prince George's County, District 16, 1918-21.
- 2 Land Records of Prince George's County, 31:371, 1907.
- United States Census, 1910, Prince George's County, District 16, #445.
- ⁴ Tax Assessments, op. cit.
- ⁵ For other examples, see P.G. #61-13, Gallant House.

See Notes, #8

10. Geographical Data	
Acreage of nominated property 33614 Sq. Feet Quadrangle name Washington East, Section E UTM References do NOT complete UTM references	Map 50 D-1 1900 L.28 Quadrangle scale
A Language Lasting Northing	Zone Easting Northing
C	D
Verbal boundary description and justification List all states and counties for properties overlapping	state or county boundaries
state code cour	
state code cour	nty code
11. Form Prepared By	
name/title Marina King, Architectural Historia	n
organization Historic Preservation Commission	date July 1986
street & number 14741 Governor Oden Bowie Driv	e telephone 952-3520
city or town Upper Marlboro	state Md.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle


Annapolis, Maryland 21401

(301) 269-2438

Chain of Title

William H. Carlton House P.G. #68-21

6120:458 12 June 1985 Deed	Eugene J. and Joan Corrado to Brian T. Wonderly. For \$62,500.00 grantors convey Lot 28 in Block R, East Hyattsville - a resubdivision of Lot 26. Contains 6,372 square feet. Address 5110 Emerson Street. Same described in 5624:564.					
5624:564 30 Dec 1982 Deed	Eva L. Hunter to Eugene J. and Joan Corrado. For \$56,000 grantor conveys:					
beed	Parcel 3: Land of Walter Brooke Hunter, also known as W. Brooke Hunter, described 474:373, Lot 26, Block R, unrecorded plat of East Hyattsville. Contains 6,372 square feet.					
474:373 21 April 1937 Deed	R. Carl Eaton and Mary E. Eaton of Edmonston to Wilbert N. Sales of Edmonston. For \$10.00 grantors convey same property obtained from William H. Carlton and Martha E. Carlton, September 15, 1922. Recorded 188:30.					
188:30 15 Sept 1922 Deed	William H. Carlton and Martha E. Carlton to R. Carl Eaton and Mary E. Eaton. For \$10.00 grantors convey a part of same land obtained from J. Harris Rogers, February 28, 1907, 31:371 - Lot measures 208.5 feet by 72 feet, together with improvements.					
31:371 28 Feb. 1907 Deed	J. Harris Rogers, unmarried to William H. Carlton - both of Hyattsville. For \$10.00 grantor conveys a lot 208.5 feet by 235.2 feet, together with all improvements. J. Harris Rogers has plan of subdivision of East Hyattsville. Poppleton Place plated by Edward R. Latimer, February 1907.					





William H. Carlton House Prince George's County, MD Marina King February 1986 South elevation Neg: MD Hist. Trust, Annapolis, MD



William H. Carlton House Prince George's County, MD Marina King February 1986 East elevation Neg: Md. Hist. Trust, Annapolis, MD



William H. Carlton House Prince George's County, MD Marina King February 1986 North elevation Neg: Md. Hist. Trust, Annapolis, MD



William H. Carlton House Prince George's County, MD Marina King February 1986 West elevation Neg: Md. Hist. Trust, Annapolis, MD